## COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Israel Aircraft Industries 1123 and 1124 (Westwind) Series Aeroplanes

AD/IAI-W/5	Galley Electrical Wiring - Inspection 12/80 and Re-Routing
Applicability:	Westwind Series S/N 239 to 298 except 241, 252, 257, 261, 264, 265, 290, 294, 295 and 297.
Document:	IAI 1124-Westwind SB No. WW-24-20 (24-03).
	Note: FAA AD No. 80-19-15 refers.
Compliance:	Part 1 - Within 10 hours time in service after 11 November 1980.
	Part 2 - To be accomplished as soon as practicable but not later than 100 hours time in service after 11 November 1980.
Background:	The FAA advise of an incident in which thrust reversers, flaps, spoilers and some lights were lost because a hot liquid container in the galley rubbed against a loom and created an electrical short circuit which resulted in a fire.