

British Aerospace BAe 3100 (Jetstream) Series Aeroplanes

AD/JETSTREAM/19

**Cracking of MLG Cylinder
Upper Attach Lug**

5/87

Applicability: As listed in the requirement document.

Requirement: Action in accordance with British Aerospace SB 32-JA860812.

Compliance: In accordance with the requirement document.

Background: During fatigue testing of the main landing gear a crack occurred in the cylinder near the upper toggle attachment lug.