

Gates Learjet 35 and 36 Series Aeroplanes

**AD/LEARJET 35/21
Amdt 1**

**Engine Hydraulic Line
Interference - Inspection**

10/83

- Applicability: All model 35 and 36 series aircraft as detailed in Gates Learjet Service Bulletins 35/36-29-1 and 35/36-29-2.
- Document: 1. Gates Learjet SB 35/36-29-1.
Note: FAA AD 83-08-3 refers.
2. Gates Learjet SB 35/36-29-2.
- Compliance: Requirement Document No. 1: Within 100 hours time in service after 30 April 1983.
Requirement Document No. 2: Within 100 hours time in service after 30 September 1983.
- Background: This directive has been raised in issue to include a further manufacturers SB related to interference between hydraulic lines and adjacent components in the tailcone area.