

Gates Learjet 35 and 36 Series Aeroplanes

**AD/LEARJET 35/23
Amdt 2**

**Flap System and Flap Sector
Mounting Brackets**

1/87

Applicability: All models Learjet with serial numbers listed in Requirement Document.

Requirement: Modify in accordance with Gates Learjet SB AMK 86-4.

Compliance: Unless already accomplished, within 100 hours time in service or at the next inspection for Maintenance Release issue after 31 January 1987 whichever is later.

Background: This Directive was initially issued due to cracking of the flap sector mounting brackets. A repetitive inspection was later included because of further cracking after inspection. This amendment now requires modification using steel sector mounting brackets and deletes the repetitive inspection.