## COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Gates Learjet 35 and 36 Series Aeroplanes

## AD/LEARJET 35/28 Crew Oxygen Plumbing and Map 2/93 Light Wire Protection

Applicability: All Learjet 35 and 36 series airplanes with serial numbers 35-001 to 35-661 inclusive

and 36-001 to 36-063 inclusive.

Requirement: Modify the cockpit map light wiring in accordance with Learjet Airplane

Modification Kit AMK 90-5 dated 11 October 1991.

Note: FAA AD 92-19-12 Amendment 39-8370 refers.

Compliance: Prior to further flight after 4 July 1993.

Background: The FAA has received a report of an in-flight fire on a Learjet Model 24 series

airplane caused by chafing of the cockpit map light wires. The electrical arcing against the oxygen mask tubing caused burn-through and the subsequent fire.

Compliance with this Directive decreases the likelihood of an in-flight fire caused by

map light wire chafing.