

Bell Helicopter Textron 412 Series Helicopters

AD/BELL 412/32	Main Driveshaft and Tail Rotor Drive Over-Temperature Indicators	10/94
-----------------------	---	--------------

- Applicability: All model Bell Helicopter Textron 412 Series Helicopters S/N 33001 through 33213, 34001 through 34024 and 36001 through 36086.
- Requirement: Action in accordance with Bell Helicopter Alert Service Bulletin 412-93-79 Rev A.
Note: Transport Canada AD CF-94-07 dated 11 April 1994 refers.
- Compliance: As specified in the Requirement Document effective from 15 September 1994.
Note: The Pilot in Command may carry out and certify in the maintenance release the Requirement Document Part II Serviceability Check required by this directive.
- Background: Bell Helicopter has advised that the self adhesive temperature indicators are a more reliable means of over temperature indication than that provided by the zinc chromate primer stripe.