



Airworthiness Directive

AD No.: 2025-0137

Issued: 27 June 2025

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

Design Approval Holder's Name:

AIRBUS HELICOPTERS

Type/Model designation(s):

AS 350 and EC 130 helicopters

Effective Date: 11 July 2025

TCDS Number(s): EASA.R.008

Foreign AD: Not applicable

Supersedure: None

ATA 04 – Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

Manufacturer(s):

Airbus Helicopters (AH), formerly Eurocopter, Eurocopter France, Aerospatiale

Applicability:

AS 350 B2, AS 350 B3, EC 130 B4 and EC 130 T2 helicopters, all serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

The ALS: AH AS 350 and EC 130 Aircraft Maintenance Manual (AMM) Chapter 04, Airworthiness Limitations Section (ALS) Revision 018 (for AS 350 B2 and AS 350 B3 helicopters), Revision 016 (for EC 130 B4 helicopters) and Revision 014 (for EC 130 T2 helicopters), as applicable.

The ASB: AH Alert Service Bulletin (ASB) AS350-62-00-0001.

The AMP: The Aircraft Maintenance Programme (AMP) contains the tasks on the basis of which the scheduled maintenance is conducted to ensure the continuing airworthiness of each operated aircraft. For aircraft operated under EU regulations, the operator or the owner ensures compliance with the AMP as stipulated in Commission Regulation (EU) [1321/2014](#).



New and/or more restrictive tasks and limitations: This includes all tasks and limitations that are new or for which a threshold and/or interval was reduced, which were introduced into the ALS, as defined in this AD, since the previous ALS revision that is currently incorporated in the AMP.

Reason:

The airworthiness limitations for AS 350 and EC 130 helicopters, which are approved by EASA, are currently defined and published in the AH AS 350 and EC 130 ALS documents. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

EASA previously issued AD 2024-0133, requiring the actions described in AH AS 350 and EC 130 AMM Chapter 04, ALS at Revision 009 for AS 350 B, AS 350 BA, AS 350 BB, AS 350 D and AS 350 B1 helicopters, Revision 016 for AS 350 B2 and AS 350 B3 helicopters, Revision 014 for EC 130 B4 helicopters and Revision 012 for EC 130 T2 helicopters.

Since that AD was issued, AH published the ALS, which contains new and/or more restrictive tasks and limitations for AS 350 B2, AS 350 B3, EC 130 B4 and EC 130 T2 helicopters. AH also published the ASB, as defined in this AD, providing instructions to determine the compliance time for the first replacement of certain parts installed on AS 350 B3 helicopters delivered before 19 May 2025.

For the reasons described above, this AD requires accomplishment of the actions specified in the ALS and determination of the compliance time for first replacement of certain parts installed on certain AS 350 B3 helicopters.

Concurrently with the issuance of this AD, EASA AD 2024-0133 is revised to remove AS 350 B2, AS 350 B3, EC 130 B4 and EC 130 T2 helicopters from its Applicability.

Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

Maintenance Tasks and Replacement of Life Limited Parts:

- (1) From the effective date of this AD, accomplish the following actions, as specified in the ALS, as applicable to helicopter model and depending on helicopter configuration:
 - (1.1) Replace each component before exceeding the applicable life limit (see Note 1 of this AD), and
 - (1.2) Within the thresholds and intervals as defined in the ALS, accomplish all applicable maintenance tasks.

Note 1: The ASB provides additional information and instructions which must be used to determine the compliance time for first replacement of certain parts installed on AS 350 B3 helicopters delivered before 19 May 2025.



Corrective Action(s):

- (2) In case of finding discrepancies (as defined in the ALS) during accomplishment of any task as required by paragraph (1) of this AD, within the compliance time specified in the ALS, accomplish the applicable corrective action(s) in accordance with the applicable AH maintenance documentation. If no compliance time is identified in the ALS, accomplish the applicable corrective action(s) before next flight. If a detected discrepancy is not identified in the ALS, before next flight, contact AH for approved instructions and accomplish those instructions accordingly.

AMP Revision:

- (3) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the limitations, tasks and associated thresholds and intervals described in the ALS, as applicable to helicopter model and depending on helicopter configuration.

Credit:

- (4) If, before the effective date of this AD, the AMP has been revised to incorporate the maintenance tasks and life limitations as specified in a previous revision of the ALS and the ASB, as applicable to helicopter model (see Note 1 to this AD), that action ensures the continued accomplishment of those tasks and limitations.

Consequently, for a helicopter to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks and limitations as specified in the ALS, as applicable to helicopter model and depending on helicopter configuration, within the compliance times as specified in the ALS or the ASB (see Note 1 of this AD), as applicable, to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks and limitations as specified in the ALS or the ASB (see Note 1 of this AD), as applicable to helicopter model and depending on helicopter configuration, into the AMP to comply with paragraph (3) of this AD.

Recording AD Compliance:

- (5) When the AMP of a helicopter has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures continued accomplishment of the tasks and limitations as required by the paragraphs (1) and (2) of this AD for that helicopter. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

Ref. Publications:

AH AS 350 B2 AMM Chapter 04 ALS Revision 018 dated 22 May 2025.

AH AS 350 B3 AMM Chapter 04 ALS Revision 018 dated 13 May 2025.

AH EC 130 B4 AMM Chapter 04 ALS Revision 016 dated 13 May 2025.

AH EC 130 T2 AMM Chapter 04 ALS Revision 014 dated 13 May 2025.



AH ASB AS350-62-00-0001 original issue dated 19 May 2025.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 28 May 2025 as PAD 25-079 for consultation until 25 June 2025. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: Airbus Helicopters Customer Support, Telephone +33 (0)4.42.85.97.89, Fax + 33 (0)4.42.85.99.66, E-mail: Airframe.Technical-Support@airbus.com, Keycopter Technical Request Management: TechnicalSupport.Helicopters@airbus.com.

