

Enstrom F-28 Series Helicopters

AD/ENST 28/16

**Tail Rotor Pitch Link Retainer and
Guide Bolt - Replacement**

10/77

- Applicability: Models F-28C and 280C fitted with the Wide Cord tail rotors and S/Nos. as listed in the requirement document.
- Requirement: 1. Inspect the P/N 28-16320 pitch link retainer in accordance with Enstrom Service Directive Bulletin No. 0040.
2. Replace the P/N 28-16320 pitch link retainer and guide bolts in accordance with Enstrom Service Directive Bulletin No. 0040 and 0043.
- FAA AD 77-15-04 refers.
- Compliance: 1. For Part 1 of the requirement document - before each flight, until part 2 is complied with.
2. For Part 2 of the requirement document - within 100 hours time in service after 30 November 1977.