COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 369/45.

McDonnell Douglas (Hughes) and Kawasaki 369 Series Helicopters

AD/HU 369/45

Tail Rotor Swashplate Bearing Locknut - Increase in Torque

6/2009

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This unique Australian AD raised in 1980 against Hughes Service Information Notice

(SIN) No. HN-150 required an increase in torque of the tail rotor swashplate bearing

locknut to prevent loosening.

Compliance was: Within 100 hours TIS after 31 March 1980.

This AD has been sufficiently promulgated for the subject tail rotor bearing locknuts to have been re-torqued; therefore this AD is considered to be no longer required.

James Coyne

Delegate of the Civil Aviation Safety Authority

24 April 2009