

McDonnell Douglas (Hughes) and Kawasaki 369 Series Helicopters

AD/HU 369/101

Oil Cooler Blower Bracket

13/99

Applicability: Model 369D, 369E, 369FF, 500N, and 600N helicopters with oil cooler blower bracket, P/No 369F5190-1, installed.

Requirement: Replace oil cooler blower bracket, P/No. 369F5190-1, with a serviceable bracket, P/No. 369F5194-1.

Note: FAA AD 99-20-12 also refers.

Compliance: Within 100 hours time in service after the effective date of this airworthiness directive.

This Airworthiness Directive becomes effective on 30 December 1999.

Background: There have been reports of cracked oil cooler blower brackets. Failure of a bracket can result in loss of cooling of engine oil and transmission oil and a subsequent forced landing.