(Civil Aviation Safety Regulations 1998), PART 39 - 105

COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/R22/10.

Robinson R22 Series Helicopters

Tail Rotor Drive Shaft Damper Clips - Replacement

5/2009

Requirement: CANCELLED.

This AD is cancelled on 7 May 2009.

Background: This unique Australian AD specified replacement of tail rotor drive shaft damper clips in accordance with Robinson SB No. 14 within 25 hours time in service after November 1981. The AD is no longer required.

AD/R22/10

David Villiers Delegate of the Civil Aviation Safety Authority

16 March 2009