

Sikorsky S-76 Series Helicopters

AD/S-76/36

**Fuselage - Engine Compartment Centre
Firewall - Inspection of No. 1 Tail Drive
Shaft for Adequate Clearance**

**3/85
TX**

Applicability: All model S-76A Helicopters.

Requirement: Sikorsky Alert S.B. 76-53-24. Sikorsky CBT-TP-84-098.

Compliance: Unless already accomplished, before further flight after 12 February 1985.

Background: A report indicates No. 1 section tail rotor drive shaft became severed due to interference with doubler P/N 76070-20057-101.