

Turbomeca Turbine Engines - Makila Series

AD/MAKILA/2

Governor Master and Auxiliary Cams

1/92

Applicability: All Makila 1A and 1A1 engines.

Requirement: Unless previously carried out action in accordance with Turbomeca Service Makila No 72.298.00.59.

Note: DGAC AD 91-226-(B) refers.

Compliance: Within 600 hours time in service from 30 November 1991 or by 31 August 1992, whichever occurs first.

Background: Engine flame out can occur when the control lever is rapidly retarded from the flight to quick reduction position.