

Document: 1. Remove torque meter boost pump P/No. 1-300-221-01 or P/No. 1-300-221-02 and replace with P/No. 1-300-221.04; or

2. FAA AD 75-22-02, Amendment 39-2385; or

Compliance: Within 200 hours time in service after 31 December 1975.