Airworthiness Directive





Issued by the Civil Aviation Authority of New Zealand in accordance with section 72I(3A) of the Civil Aviation Act. An Airworthiness Directive (AD) contains regulatory information which is mandatory. An operator of an aircraft must not operate the aircraft unless the operator complies with every applicable AD issued by the Director in accordance with section 72I(3A) of the Civil Aviation Act. An AD is issued where the Director believes on reasonable grounds that an unsafe condition exists in an aircraft or aeronautical product.

* DCA/750XL/17A Reversionary Attitude Indicator - Installation

Applicability: Pacific Aerospace 750XL aircraft, all S/N operating under Instrument Flight Rules (IFR).

Note: Pacific Aerospace 750XL aircraft eligible for operation under IFR require a reversionary

attitude indicator. DCA/750XL/17A revised to introduce Pacific Aerospace Mandatory Service

Bulletin (MSB) PACSB/XL/074 issue 2, dated 4 November 2014.

Requirement: To ensure continued safe flight under IFR in the event of loss of the primary attitude indication,

accomplish the requirements in Pacific Aerospace Mandatory Service Bulletin (MSB)

PACSB/XL/074 issue 2, dated 4 November 2014.

(Compliance with FAR 23.1309)

Compliance: Before the next IFR flight.

Effective Date: DCA/750XL/17 - 6 November 2014

DCA/750XL/17A - 10 November 2014

Background: This AD with effective date 10 November 2014 is prompted by a recent determination that

certain PAL750XL aircraft were inadvertently manufactured with instrument panels with only one Attitude Indicator (AI). A second AI is required for PAL750XL operating under Instrument

Flight Rules (IFR).

The AD mandates the installation of either a second AI, or the enablement of Reversionary Attitude mode in the Sandel Electronic Horizontal Situation Indicator (EHSI), if fitted, when

operating under IFR.

Owen Olls

Airworthiness Specialist

Delegate of the Civil Aviation Authortiy of New Zealand

6 November 2014