

DH 82 (Tiger Moth) Series Aeroplanes

**AD/DH 82/17 Lateral Fuselage Tie Rods - Removal
and Replacement – NOT ISSUED**

Following industry consultation via CASA Proposed Airworthiness Directive PAD/DH 82/17, the United Kingdom Civil Aviation Authority issued AD G-2014-0001-E to address this unsafe condition. As the United Kingdom is the state of design for these aircraft, AD/DH 82/17 was not issued.