

Embraer EMB-110 (Bandeirante) Series Aeroplanes

**AD/EMB-110/39
Amdt 2**

Trim Tab Actuator Attachments

12/87

Applicability: All models.

Requirement: Action in accordance with Embraer SB110-027-0083.

Compliance: Within 500 hours time in service after 3 December 1987.

Background: The Department has received reports of fractured spring pins on Australian aircraft. Pin failure could result in control surface flutter. Amdt 1 of this Directive extended compliance to all trim tab actuators. Amdt 2 of this Directive references SB110-027-0083 which replaces existing spring pins with solid pins.