

Fuji FA-200 Series Aeroplanes

**AD/FA-200/9
Amdt 1**

**Engine Driven Fuel Pump
Outlet Tee - Replacement**

3/83

Applicability: All model FA-200-180 with S/No. 12 and subsequent.

Requirement: Install new engine driven fuel pump outlet tee P/No. AN783-6.

Note: Fuji SB No. 200-004 and Japanese CAB AD TCD-2213-82 refer.

Compliance: Within 100 hours time in service after 31 March 1983 and thereafter at intervals of 3000 hours time in service.

Background: Instances of fatigue cracking have been reported by the manufacturer. This AD has been amended to restrict the service life of the component.