COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/FN-333/2.

SIAI Marchetti FN-333 (Riviera) Series Aeroplanes

AD/FN-333/2 Fuel Solenoid Valve Relocation - Flexible 6/2009 Hose Installation

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This unique Australian AD raised prior to 1970 against SIAI Marchetti Service

Bulletin (SB) No. 333-5 (dated 22 October 1964) required a modification to relocate the fuel solenoid valve and replace metallic lines to and from the solenoid and relief

valves with flexible hoses.

Compliance was: Forthwith.

This AD has been sufficiently promulgated for the affected aircraft to have been modified by now; therefore this AD is considered to be no longer required.

James Coyne

Delegate of the Civil Aviation Safety Authority

24 April 2009