

Grob G115 Series Aeroplanes

---

**AD/GROB 115/4**

**Firewall Bonding Lead**

**11/91**

Applicability: All G115A series aircraft S/No 8091 through 8109 inclusive, except S/Nos 8097, 8100 and 8102.

Requirement: Action in accordance with the technical requirements of GROB G115 Service Bulletin TM 1078-18.

Compliance: Within 25 hours Time in Service after 14 November 1991.

Background: Grob have advised that during engine start, there is a possibility that a high resistance may occur at the bonding lead assembly mounted at the firewall.

This may cause a reverse current to occur which may damage wiring and other aircraft components. To prevent this, the existing bonding bolt plate must be replaced with a modified bonding bolt plate (P/No 115-9006).