

Grob G115 Series Aeroplanes

AD/GROB 115/6

Elevator - Lever

5/95 DM

Applicability: All Grob G115, G115A and G115B.

Requirement: Carry out a dye penetrant inspection of the elevator lever (P/N 115-3571) for cracks in accordance with Grob G115 Service Bulletin TM 1078-29.

Note: LBA AD 93-135 Grob refers.

Compliance: Initially inspect within 5 hours time in service from 29 March 1995.

Re-inspect at intervals not to exceed 100 hours time in service.

Background: A report has been received of cracks in the elevator lever. Precautionary inspections will ensure that the airworthiness of the aircraft is maintained.