COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Aerospatiale GY 80 (Horizon) Series Aeroplanes

AD/GY80/7 Propeller Governor Oil Inlet Union - Replacement 6/79

Applicability: All GY80 aircraft fitted with variable pitch Hartzell propeller.

Document: Aerospatiale Horizon SB No. 37.

Compliance: Within 100 hours time in service after 31 July 1979.

Background: This Directive is issued as the result of overseas notification of oil loss caused by

failure of the crankcase mounted union.