

Mitsubishi MU-2 Series Aeroplanes

---

**AD/MU-2/30                      Engine Electrical Harness - Inspection and                      1/84**  
**Replacement of P/No MS25471 Electrical Cable**

Applicability:    MU-2B-10/-15/-20/-25/-26 S/Nos 005 to 347 (except S/Nos 313 and 321).  
                          MU-2B-30/-35/-36 S/Nos 501 to 696 (except S/Nos 652 and 661).

Document:        Mitsubishi Heavy Industries SB No. 191.

1. Inspect engine electrical harness in accordance with SB No. 191.
2. Replace unacceptable electrical wiring Part No. MS 25471 in accordance with SB No. 191.

*Note: JCAB AD No. TCD 2113-82 refers.*

Compliance:    Part 1 - Within 100 hours time in service after 31 January 1984 and thereafter at intervals not exceeding 100 hours time in service if required.

Part 2 - Within 300 hours time in service after 31 January 1984.

Background:     The conducting portion of the electrical cable has been found protruding through the insulation.