

Mitsubishi MU-2 Series Aeroplanes

---

**AD/MU-2/37                      Flap Flexible Shaft Sealing and Torque Check                      12/85**

Applicability: All models MU-2B/-10/-15/-20/-25/-26 with S/Nos. 008 to 347 except S/Nos. 313 and 321. All models MU-2B-30/-35/- 36 with S/Nos.501 to 696 except S/Nos. 652 and 661.

Requirement: Action in accordance with Mitsubishi SB No. 198.

*Note: JCAB AD No. TCD-2451-85 refers.*

Compliance: At the next scheduled inspection for Maintenance Release issue after 31 December 1985.

Background: The manufacturer reports failures of the flexible drive shaft attributable to ingress of moisture.