

Mitsubishi MU-2 Series Aeroplanes

AD/MU-2/55

Emergency Gear Down Gearbox

8/94

Applicability: All MU-2B-10, -15, -20, -25, -26 S/N 008 through 347, except S/N 313 and 321, MU-2B-30, -35 and -36 S/N 501 through 696, except S/N 652 and 661.

Requirement: Action in accordance with Mitsubishi MU-2 Service Bulletin No 219.

Note: JCAB AD TCD-3942-94 refers.

Compliance: Unless previously carried out within 100 hours time in service from 31 July 1994.

Background: The manufacturer has advised that a lower pin of an emergency gear down gearbox has fallen out of the bracket housing.