

Partenavia P68 Series Aeroplanes

AD/P68/12

**Propeller Control Rod End - Inspection
and Replacement**

11/78

Applicability: All models P68 and P68B with S/Nos. below 160.

Document: Partenavia SB No. 37, Revision 1.

Compliance: Within 50 hours time in service after 17 October 1978 and thereafter at intervals not exceeding 50 hours time in service until Part 2 of Partenavia SB No. 37, Revision 1 is completed.