

Partenavia P68 Series Aeroplanes

---

**AD/P68/18**                      **Oil Cooler Elbow Fitting - Replacement**                      **12/79**

Applicability: All models P68 and P68B with S/Nos. 182 and below, except 74, 89, 133, 142, 155, 163 and 171.

Requirement: Replace the oil cooler left hand elbow fitting P/N AN822-6-6D in accordance with page No. 3 of Partenavia SB No. 45.

Compliance: Within 100 hours time in service after 31 December 1979.

Background: In order to reduce strain on hose and fitting the oil cooler left hand elbow is replaced with an elbow of a more suitable angle.