

Piper PA-18 and 19 (Super Cub) Series Aeroplanes

AD/PA-18/11 Lower Horizontal Stabiliser Brace Wire Fuselage 12/81
Amdt 1 Attachment Tab - Inspection and Modification

Applicability: All models PA-18-150 with S/Nos. 18-8602 to 18- 8109013.

Document: Piper Service Bulletin No. 706A. (FAA AD 81-06-80 Letter of 13-3-81 refers).

Note: Aircraft modified to Piper SB No. 706 do not require further rework.

- Compliance:
1. Unless already accomplished, inspect within 100 hours time in service after 31 December 1981.
 2. Unless already accomplished, modify within 300 hours time in service after 31 December 1981.

Background: Revision "A" of Piper SB introduces a revised template shape for horizontal stabiliser brace wire additional support plate.