

Piper PA-22 (Tri-Pacer and Colt) Series Aeroplanes

---

**AD/PA-22/27                      Rapid Throttle Movement - Warning Placard                      6/73**

Applicability:    Models PA-22-150, PA-22S-150, PA-22-160, PA-22S-160 fitted with Lyc. 0-320 engines equipped with Marvel Schebler carburettors model MA-4SPA P/Nos. 10-3678-11, 10-3678-12, 10-3678-32; and other PA-22 series aircraft which have been modified to these engines/carburettor configurations.

Requirement:    1.    Attach the following placard to the instrument panel near the throttle control and in full view of the pilot using letters of 1/8" maximum size:

“DO NOT OPEN THROTTLE RAPIDLY - IDLE TO FULL THROTTLE  
IN 2 SECONDS MINIMUM”.

*Note: The placard may be fabricated by the owner or operator.*

or 2. FAA AD 73-9-6.

Compliance:    Within 10 hours time in service after 9 May 1973.