

Piper PA-32 (Cherokee Six) Series Aeroplanes

---

**AD/PA-32/64**                      **Fuel Flow Indicator Line - Replacement**                      **9/79**

Applicability:    Model PA-32RT-300T with S/Nos. 32R-7887001 to 32R-7987124.

Document:        1. Piper SB No. 652; or  
                      2. FAA AD 79-13-04, Amendment 39-3500.

Compliance:     Within 25 hours time in service after 19 July 1979.

Background:     There are overseas reports of broken fuel flow indicator lines which have resulted in fuel leakage, engine power loss and one instance of a forced landing.