

Piper PA-36 (Pawnee Brave) Series Aeroplanes

AD/PA-36/22

Forward Fuselage Tubes

6/86 T

- Applicability:** All models PA-36-300 with S/Nos. 36-7760001 through 36-8160023 and PA-36-375 with S/Nos. 36-7802001 through 36-8302025 which have not been modified in accordance with Piper Service Bulletin No. 828.
- Document:** Inspect the forward fuselage tubing at the engine mount attachment areas in accordance with Piper Service Bulletin No. 828.
- Compliance:** Prior to further flight after 12 May 1986 and thereafter at intervals not exceeding 25 hours time in service.
- Background:** The manufacturer reports that cracks have been found in the forward fuselage tubing weld clusters at the engine mount attachment locations. If undetected, this could result in engine/mount separation.