

Piper PA-38 (Tomahawk) Series Aeroplanes

---

**AD/PA-38/14**                      **Control Column Installation - Modification**                      **11/79**

Applicability:    All models PA-38-112 with S/Nos. 38-78A0001 to 38-79A1160.

Document:        Piper SB No. 661.

Compliance:    Unless already accomplished, within 100 hours time in service after 30 November 1979.

Background:     It has been reported to the manufacturer that roughness or binding of the control shaft in the instrument panel can occur at the extremes of control movement.