

Robin Aviation Series Aeroplanes

AD/ROBIN/11

Carburettor Inlet Fitting

7/89

Applicability: All models equipped with Lycoming O-235, O-320 or O-360 series engine.

Requirement: Action in accordance with Avions Pierre Robin Service Bulletin No 112.

Note: DGAC AD 89-052(A) refers.

Compliance: By 26 May 1989.

Background: The manufacturer requires inspection and immediate replacement of the inlet fitting if leaks are detected. If no leaks are evident fitting must be replaced at next 50 hourly inspection.