

Robin Aviation Series Aeroplanes

AD/ROBIN/15

Lateral Console Panel

7/92

Applicability: ATL, all types, to S/No 89 inclusive, except S/No 22, 28, 53, 71 and 82.

Requirement: Action in accordance with ROBIN SA SB No 7.

Note: DGAC AD 91-018(A) refers.

Compliance: Unless already accomplished; prior to further flight after 30 June 1992 if contact is evident, if no contact is evident accomplish modification prior to 31 July 1992.

Background: The DGAC requires an inspection and modification in order to prevent contact between the rudder pedals and the lateral console panel which could lead to the rudder pedals jamming.