

Robin Aviation Series Aeroplanes

AD/ROBIN/19

Throttle Control

9/94

- Applicability: Model ATL, all types except ATL “L”, with serial number range of 110 and above.
- Requirement: Modify the throttle lever control support in accordance with ROBIN Service Bulletin ATL No.9 R1.
- Note: DGAC AD 93-118(A)R1 refers.*
- Compliance: Within 25 hours time in service after 18 August 1994.
- Background: A report was received of a throttle cable casing stop failure at the control lever in the cabin.