

Robin Aviation Series Aeroplanes

AD/ROBIN/20	Main Gear Torque Link Attachment	13/94
--------------------	---	--------------

Applicability: Model HR100/250TR and HR100/285TR.

Requirement: Action in accordance with Avions Pierre Robin Service Bulletin 134.

Note: DGAC AD 94-129(A) refers.

Compliance: Unless already accomplished, within 25 hours time in service after 8 December 1994, and thereafter at intervals as specified in the Requirement Document.

Background: The DGAC requires an inspection in response to field reports of cracks on the strut torque link welded attachment points.