

Robin Aviation Series Aeroplanes

AD/ROBIN/23

Anti-Tab Control

7/95

Applicability: All Model R 2000 and HR 200 aircraft, serial numbers 250 through 271.

Requirement: Action in accordance with Avions Pierre Robin Mandatory Service Bulletin 137.

Note: DGAC AD 94-183(A)R1 refers.

Compliance: Unless already accomplished, within 100 hours time in service after 22 June 1995.

Background: The DGAC requires installation of a friction lock device on the sliding stop tube in order to improve the operating condition of the anti-tab control.