

SIAI Marchetti S205 and S208 Series Aeroplanes

AD/SM-205/23

CANCELLED

2/86

Background: It is considered that cracking of the main landing gear brackets, P/Nos 205-3-033-18 and 205-3-034-18, can now be adequately covered by normal periodic maintenance. Operators should note that replacement brackets of an improved design are now available. The manufacturer advises that these should eliminate the cracking problem. Refer SIAI Marchetti SB 205B37D.