

Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes

AD/SWSA226/79

Control Column Pitch Pivots

1/98

CANCELLED.

This airworthiness directive was issued in response to the failure of one of the control column pitch pivot bearings, which resulted in little, if any, remaining pitch authority. The manufacturer has now introduced a service life limit for the pitch pivot bearing, part number CF5/8-S, in the airworthiness limitations section of the aircraft maintenance manual. Compliance with the service life of 10 000 hours for the CF5/8-S pitch pivot bearing is considered mandatory. Accordingly, this directive is cancelled.