

Aerospatiale (Socata) TB9 and TB10 (Tobago) Series Aeroplanes

AD/TB10/8

Engine Mounts

1/87 DM

Applicability: All aircraft with engine mounts TB 10.51.000.000.

Requirement: Action in accordance with Aerospatiale Socata SB 16/1.

Compliance: Within 50 hours time in service after 17 December 1986 and thereafter at intervals not exceeding 50 hours time in service until modified.

Background: The manufacturer reports cracking of the engine mount weld clusters.