

Aerospatiale (Socata) TB9 and TB10 (Tobago) Series Aeroplanes

AD/TB10/10

Hydraulic Brake Line Clearance

11/87

Applicability: All models TB9 and TB10 up to S/No 755 inclusive, except S/Nos 630, 631, 634, 636, 643, 648, 649, 656, 657, 658, 659, 661, 662, 663, 664, 750, 751, 752 and 753.

Requirement: Action in accordance with Aerospatiale Socata SB No.33.

Note: Bureau Veritas AD 87-118(A) refers.

Compliance: Within 100 hours time in service or at the next scheduled inspection for maintenance release issue after 30 October 1987 whichever is the earlier.

Background: The manufacturer has reported instances of the cockpit hydraulic brake lines being damaged by the aileron and rudder control rods.