

Aerospatiale (Socata) TB9 and TB10 (Tobago) Series Aeroplanes

---

**AD/TB10/15**                                      **Oil Cooler Inlet And Outlet Elbows**                                      **1/91**

Applicability:    All model TB9 and TB10 aircraft.

Requirement:    Action in accordance with Socata Service Bulletin NR 50-1.

*Note: DGAC AD 90-143(A) refers.*

Compliance:    Prior to 31 January 1991.

Background:    Leakage from the oil cooler inlet and outlet elbow has resulted in total engine oil loss.