

Aerospatiale (Socata) TB9 and TB10 (Tobago) Series Aeroplanes

AD/TB10/28 **Upper Attachment of Front Seat Belts** **11/96 DM**

Applicability: S/Nos. 1 to 1701, 1707 to 1750, 1758 to 1763, 1767, 1768, and 1769.

Requirement: For TB9 aircraft not equipped with upholstery on the upper duct post:

- action in accordance with Socata SB 10-104-25.

For TB9, TB10 and TB200 aircraft with upholstery on the upper duct post:

- action in accordance with Socata SB 10-103-25.

Note: DGAC ADs 96-142(A) and 96-143(A) refer.

Compliance: Within 50 hours time in service, or 30 days, after 14 August 1996 whichever occurs first.

Background: This Directive is issued to ensure the integrity of the upper attachment of the front seat belts.