COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

AD/TB20/11 Hydraulic Brake Line Clearance 11/87

Applicability: All model TB20 and TB21 up to S/No 755 inclusive, except S/Nos 630, 631, 634,

636, 643, 648, 649, 656, 657, 658, 659, 661, 662, 663, 664, 750, 751, 752 and 753.

Requirement: Action in accordance with Aerospatiale Socata SB No 33.

Note: Bureau Veritas AD 87-118(A) refers.

Compliance: Within 100 hours time in service or at the next scheduled inspection for maintenance

release issue after 30 October 1987 whichever is the earlier.

Background: The manufacturer has reported instances of the cockpit hydraulic brake lines being

damaged by the aileron and rudder control rods.