

Aerospatiale (Socata) TB20 (Trinidad) Series Aeroplanes

---

**AD/TB20/19**

**Oil Cooler Inlet and Outlet Elbows**

**1/91**

Applicability: All model TB20 and TB21 aircraft.

Requirement: Action in accordance with Socata Service Bulletin NR 50-1.

*Note: DGAC AD 90-143(A) refers.*

Compliance: Prior to 31 January 1991.

Background: Leakage from the oil cooler inlet and outlet elbow has resulted in total engine oil loss.