Aerospatiale (Socata) TBM 700 Series Aeroplanes

AD/TBM 700/1Battery Overheating Indication5/93Applicability:TBM 700 series airplanes identified in TBM 700 Socata Mandatory Service Bulletin
No. 70-026-24 dated February 1993.Requirement:Action in accordance with TBM 700 Socata Mandatory Service Bulletin No.
70-026-24 dated February 1993.Note:DGAC AD 93-019(B) dated 3 March 1993 refers.Compliance:Within 100 hours time-in-service from 29 April 1993.Background:Compliance with this Directive will correct a wiring discrepancy in the "Battery
Overheat" indication circuitry.