

Aerospatiale (Socata) TBM 700 Series Aeroplanes

AD/TBM 700/8

Propeller Control

13/94

Applicability: All TBM 700 series aircraft within the S/N 1 to 22, 24 to 92 inclusive.

Requirement: Action in accordance with Socata TBM 700 Service Bulletin 70-042-76.

Note: DGAC AD 94-109-(B) refers.

Compliance: Within 100 hours time in service from 8 December 1994.

Background: To improve the governor control the manufacturer requires the propeller governor screws to be lockwired.