

Aerospatiale (Socata) TBM 700 Series Aeroplanes

---

**AD/TBM 700/18**

**Oxygen Generators**

**11/98 DM**

**Applicability:** TBM 700 series aeroplanes, serial number 1 and up, without Socata modification No 70-099-35 incorporated.

**Requirement:** Replace the striker pin and install a washer on each oxygen generator in accordance with Socata Mandatory Service Bulletin 70-046-35 dated May 1998.

*Note: DGAC Telegraphic AD T98-195 (A) refers.*

**Compliance:** At the next scheduled maintenance inspection, but no later than 11 September 1998.

This Airworthiness Directive becomes effective on 12 August 1998.

**Background:** This directive requires the replacement of the oxygen generator striker pin which decreases the likelihood of the striker pin failing to release the striker and the oxygen generator not operating.