

Aerostar (Piper/Ted Smith) 600 and 700 Series Aeroplanes

---

**AD/TSA-600/17**  
**Amdt 2**

**MLG Scissors Assembly**

**7/84**

CANCELLED.

Background: The 400076-503 replacement torque link has provided little improvement in service over the -501 and -01 links with one failure and six instances of cracking being recorded in Australia. Therefore the replacement requirement of this AD has been deleted while new inspection requirements have been promulgated in AD/TSA-600/33.