

Victa and A.E.S.L. Airtourer Series Aeroplanes

AD/VAT/9 Aileron Mass Balance Attachment - Inspection 11/63

- Applicability: Victa Airtourer 100 and 115 with S/Nos. 5 to 49 not incorporating Mods. B75 or B118.
- Document: Victa SB No. 18.
- Compliance: Inspect at intervals not exceeding 100 hours time in service, after 1 September 1971.